





BAXALL

Technical Tip

| | |
|--------------|--|
| Product Type | Keyboards |
| Product Item | All |
| Symptom | Keyboards are conflicting due to incompatibility |
| Solution | <ol style="list-style-type: none">1) Disconnect the power from your keyboard2) Reconnect the power3) Within 5 seconds press the keys below simultaneously  AND 4) The LCD display should change to: Special Config5) Within 5 seconds press the reverse play key6) The LCD display should change to Change KBD Id7) Within 5 seconds enter the new Id number (1-9) and press the 'Enter' key.8) The LCD display should change to Change KBD ID New SELFUNT = 00n (Where n is the new number) |

| | | | |
|--------|--------------|------|----------|
| Author | Simon Hooton | Date | 17/11/05 |
|--------|--------------|------|----------|